



Annual Operation Plan

Name of ULB: Gazipur City Corporation (GCC)

Financial Year: 2025-2026

Subject Asset			Work Specification			Management		
ID No.	Name	Asset Type	Item	Volume of Work / Input		Estimated Cost (Lakh Taka)	Source of Fund	Responsible Section
1	2	3	4	5	6	7	8	9
GCC-12	RCC Drain Cleaning from Gacha Road to Hazi Abdul Latif Primary School & Link Road. Ch.0+000 to 720	Drain	Drain Cleaning	720	m	1.77	GCC Own	Engineering Section
ICGP B1 GCC-02	Construction of RCC drain along the side of Maleker bari road (Dhaka Mymansingh Highway) to Bashan sarak Via Ozarpara & Haque Market and Link Ch.00 to 2+305.	Drain	Drain Cleaning	2305	m	5.98	GCC Own	Engineering Section
GCC-16	Construction of RCC drain from Mission gate to Nager Halot Jora Bridge. Ch.0+000 to 1+250	Drain	Drain Cleaning	2366.250	Cum	31.14	GCC Own	Engineering Section
ICGP B1 GCC04	Construction of Drain (RCC/Pipe) along the side of the road from Rajendropur BRAC center gate to MirzapurBazar canal	Drain	Drain Cleaning	7600.38	Cum	87.633	GCC Own	Engineering Section
ICGP B1 GCC-16	RCC Drain Cleaning from Gacha Road (Fokir Market) to Hazi Abdul Latif Primary School & Link Road. Ch.0+000 to 757	Drain	Drain Cleaning	757	m	2.31	GCC Own	Engineering Section

ICGP B2 GCC-05(b)	b) Construction of RCC drain at Kashimpur to Sreepur connecting road (Zitermour to Mother textile) (Ch.0+000 to 4+500) & Link	Drain	Drain Cleaning	3258.28	Cum	39.45	GCC Own	Engineering Section
ICGP B2 GCC-13	Construction of drain along the side of Nowzour to Zirani Bazar (starting from Zitermour to west direction up to 6.75 Km). (Ch. 00+000 to 6+750)	Drain	Drain Cleaning	3682.123	Cum	45.18	GCC Own	Engineering Section
ICGP B2 GCC-18	Construction of RCC drain (BADC mor to Mother Textile) from Mission gate to Nager Halot Jora Bridge. Ch.0+000 to 1+250	Drain	Drain Cleaning	2766.250	Cum	37.14	GCC Own	Engineering Section
ICGP B2 GCC-14:	Installation of 1 (One) Nos production Tube wells, Pumps house, Necessary electrical work with 10.00 km distribution tube pipe line at Zone-02 respectively.	WSS	Pump operational cost	Per month	month	0.05	GCC Own	Engineering Section
ICGP B2 GCC 22	Repairing of road by Rcc Road from Simoltoli to Naga Bridge.	Drain	Drain Cleaning Disposing surplus excavated soils of all types outside the site premises. Manhole cover	474.000 468.200 8768.00	Cum Each	7.34	GCC Own	Engineering Section

Prepared by

Date: **Sohrab Hossain**
Sub-Assistant Engineer
Gazipur City Corporation

MD. MYDUL ISLAM
Executive Engineer (Civil)
Zone-4
Gazipur City Corporation

Approved by

(এম হারুনুর রশীদ)
তত্ত্বাবধায়ক প্রকৌশলী (চ: দা:)
গাজীপুর সিটি কর্পোরেশন
গাজীপুর।

Annual Maintenance Plan

Name of ULB: Gazipur City Corporation (GCC)

Financial Year: 2025-2026

Subject Asset				Work Specification					Schedule			Management		
ID No.	Name	Asset Type	Present Condition	Type of Work	Detail of Work	Location/Chain age From – To (km)	Required Work Volume (unit)		Estimat ed Cost (Lakh Taka)	Work Start from (dd/mm/yyyy)	Work End at (dd/mm/yyyy)	Priority Rank	Source of Fund	Responsible Section
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
GCC-21	a) Improvement of BC road from Mosher market to Kaler Vita mosque via Maglal Mosque. B) Improvement of BC road from Mauglal Dr. Samsul House south side to Kaler Vita mosque via Kholapara Govt. Primary School Ch.0+000 to 2+500.	Road	Poor	Routine Repair	Earth filling, sand filling, End Edging, sub base, Base coarse, wearing coarse, palisading work etc....	(Various location)	EFW(CE): 157.150 Sand Filling: 61.30 SBBC: 44.725 EE(75mm): 330.0 S&SBC: 75.339 PCHD: 260.5 15mmSC: 320.0 DCPM: 13.660 RCC(P+SP): 55.0 RCC(P+DP): 48.0 etc.....	Cum Cum Cum m Cum Sqm Sqm Cum M M	21.23	01/12/2025	30/05/2026	1	GCC Own	Engineering Section
GCC-23(C)	c) Improvement of road by BC from Bagja Diss pukur par to Barek Mollah & Joyartek Primary school to east side Nazem Uddin home. Ch.00 to 1400m.	Road	Poor	Routine Repair	Earth filling, sand filling, End Edging, sub base, Base coarse, wearing coarse, palisading work etc....	(Various location)	EFW(CE): 120.150 Sand Filling: 61.30 SBBC: 41.725 EE(75mm): 310.0 S&SBC: 58.339 PCHD: 281.5 15mmSC: 310.0 DCPM: 11.660	Cum Cum Cum m Cum Sqm Sqm Cum	19.23	01/12/2025	30/05/2026	2	GCC Own	Engineering Section

							RCC(P+SP): 57.0 RCC(P+DP): 45.0 etc.....	M M							
ICGP B1 GCC05R	Repairing & Widening of road by BC from Bilashpur Bot Tola to Porabari Bazar of Dhaka- Maymensingh road to via Salna Bazar & Jolarpar Bazar (Bilashpur Bottola to Salna Bazar to Jolarper Bazar to Porabari Bazar	Road	Poor	Routine Repair	Box Cutting, sand filling, sub-base, base course, wearing course, palisading work etc....		BC&SGP(450mm): 2025.2 Sand (FM 0.80) : 810.080 SBBC(FM<0.5): 405.040 EE(125mm): 664.000 WBMC: 673.380 CWBM(ISSM): 506.300 PCHD@1.2: 3416 DCPM: 121.512 EFW(CE): 582.66 Earth work : 2.16 PS: 120.00 Deformed Bar: 1262.736	Sqm Cum Cum m Cum Cum Sqm Cum Cum Cum Sqm Kg	158.77	01/12/2025	30/05/2026	3	GCC Own	Engineering Section	
ICGP B2 GCC-04R	Repairing & Widening of Tongi Vadam road by RCC work with pipe drain and Link road.	Road & Drain	Poor	Emergency	Earth Filling, Tack coat, wearing coarse, Inspection pit wall up, Top slab, manhole cover etc.	Ch. 0.0-2900.0 (Various location)	EFW(CE): 600 TCHD: 16690 25mmDC: 16690 BW (1:4): 48.138 RCC-30SCCM: 65.088 Deformed Bar: 9713.480 Manhole cover: 58 etc.....	Cum Sqm Sqm Cum Cum Kg No's	178.0	01/12/2025	30/05/2026	4	GCC Own	Engineering Section	
ICGP B1 GCC02	Repairing & widening of Road from Mazu khan bazar to Meghdubi Bi-pass road bia kironartack at Pubail by BC along with 1 box culvert.	Road	Poor	Routine Repair	BC &SGC(450mm), Earth filling, EE(125mm End Edging, sub base, Base coarse, wearing coarse, etc....	Ch. 0.0-2500.0 (Various location)	BC &SGC(450mm): 385 EE(125mm): 235.00 SBBC: 78.06 CWBM (ISSM): 51.75 PCMD@1.2 : 385.00 40mmBC(BG-60/70): 385 TCMD@.75: 933.94	sqm m Cum Cum sqm sqm sqm	36.407	01/12/2025	30/05/2026	5	GCC Own	Engineering Section	

							EFW(CE) 58.05 Brick (BP-TW) 10 etc,.....	Cum m							
ICGP B1 GCC 04	Construction Of Drain (RCC / Pipe) along the side of the road from Rajendropur BRAC center gate to Mirzapur Bazar Cannel	Drain	Poor	Routine Repair	Drain top slab casting, RCC work.		RCC-25SCCM: 19.75 Deformed Bar: 974.65	Cum Kg	7.25	01/12/2025	30/05/2026	6	GCC Own	Engineering Section	
ICGP B2 GCC 06	Repairing and widening of joy Bangla Road By RCC-BC (Borobari to meghdubi By- Pass via Akkas Market)	Road	Poor	Routine Repair	Earth work, sand filling, sub base, WBMBC, PCC, Brick work, RCC work etc.....	Ch. 0.0- 3620.0 (Various location)	BC &SGC(450mm) : 487 Sand filling EE(125mm): 215.00 SBBC: 95.00 S&SBC(WG) : 128 CWBM (ISSM): 96.80 PCMD@1.2 : 487.00 40mmBC(BG-60/70): 921 TCMD@.75: 921 EFW(CE) 64.50 etc,.....	Sqm Cum m Cum Cus sqm Cum sqm sqm Cum	28.407	01/12/2025	30/05/2026	7	GCC Own	Engineering Section	
ICGP B1 GCC-15	RCC Road Repairing by Seal Coat from Gacha Road (Fokir Market) to Hazi Abdul Latif Primary School & Link Road.	Road	Poor	Routine Repair	TCMD@0.75 DCPM	Ch. 0.0-552.0 (Various location)	TCMD@0.75: 2776.72 DCPM : 138.836	Sqm Cum	39.76	01/12/2025	30/05/2026	8	GCC Own	Engineering Section	
GCC 07	Repairing and widening of road from Surabari Rice mill to Kashimpur- Sreepur Road Kazi Market Mr.Malek	Road	Poor	Emergency	Earth work, sand filling, sub base, WBMBC, PCC, Brick work, RCC work etc.....	Ch. 0.0- 1850.0 (Various location)	Earth work: 30.24 Sand Filling: 65.82 SBBC: 40.32 WBMBC: 71.5	Cum Cum Cum Cum Cum	31.05	01/12/2025	30/05/2026	9	GCC Own	Engineering Section	

[Handwritten signature]

[Handwritten signature]

	House via Shaildubi Member Market. (RCC Part)						PCC: 4.732 BW(1:4): 18.9 RCC-25SCBP: 53.76 Deformed Bar: 2735.04 etc,.....	Cum Cum Kg							
ICGP B2 GCC-05(a)	a) Repairing & Widening of BC Road from Kashimpur to Sreepur connecting road (UP to Mother Textile). (RCC Road Ch. 0+000-4+500)(Link-1 BC Road Ch.0+380-1+277.7) and 530m link-2 RCC road with side drain (Engineer bari road starting from Gacha polasona main road)	Road	Poor	Emergency	Earth work, sand filling, sub base, WBMBC, PCC, Brick work, RCC work etc.	Ch. 0.0-4400.0 (Various location)	Earth work: 15.12 Sand Filling: 72.198 SBBC: 69.048 WBMBC: 122.444 PCC: 2.363 BW(1:4): 9.45 RCC-25SCBP: 92.064 Deformed Bar: 4674.551 etc,.....	Cum Cum Cum Cum Cum Cum Kg	58.939	01/12/2025	30/05/2026	10	GCC Own	Engineering Section	
ICGP B2 GCC-05(b)	b) Construction of RCC drain at Kashimpur to Sreepur connecting road (Zitermoor to Mother textile) (Ch.0+000 to 4+500) & Link	Drain	Poor	Routine repair	Drain top slab casting, RCC work.	Ch. 0.0-4400.0 (Various location)	RCC-25SCCM: 43.94 Deformed Bar: 4672.76 Etc.....	Cum Kg	18.83	01/12/2025	30/05/2026	11	GCC Own	Engineering Section	
GCC-10	Repairing & widening of Khapara road (Ch-0+00 to Ch-3+810) By RCC Work	Road & Drain	Poor	Routine Repair	Box cutting, sand filling, sub base, tac-coat, wearing coarse, RCC work etc.	Ch. 0.0-2000.0 (Various location)	BC&SGC(450mm): 62 Sand Filling: 26.576 SBBC: 11.0 TCHD: 7000.0 25mmDC: 7000.0 RCC-30SCBP: 22.5 SBFS: 13.750	Sqm Cum Cum Sqm Sqm Cum Sqm	73.05	01/12/2025	30/05/2026	12	GCC Own	Engineering Section	

							BW (1:4): 5.1 Earth work: 28.760 RCC-30SCCM: 17.5 Deformed Bar: 3934.920 etc,.....	Cum Cum Cum Kg							
GCC-06	RCC Repairing by BC from Dhaka-Mymensingh Road to Bogar Tek Bridge at Joy Bangla Road.	Road	Poor	Routine Repair	TCMD@0.75 DCPM	Ch. 0.0-1800.0 (Various location)	TCMD@0.75: 8352.000 DCPM : 417.600	Sqm Cum	129.06	01/12/2025	30/05/2026	13	GCC Own	Engineering Section	
GCC-11	Construction of RCC Drain along side of Khapara road last part (up to Tilargati road) Ch. 1+375 to Ch-3+810	Road & Drain	Poor	Routine Repair	Box cutting, sand filling, sub base, tac-coat, wearing coarse, RCC work etc.	Ch. 0.0-2000.0 (Various location)	BC&SGC(450mm: 55 Sand Filling: 23.576 SBBC: 11.0 TCHD: 7000.0 25mmDC: 7000.0 RCC-30SCBP: 11.5 SBFS: 20.750 BW (1:4): 3.1 Earth work: 23.760 RCC-30SCCM: 16.5 Deformed Bar: 3434.920 etc,.....	Sqm Cum Cum Sqm Sqm Cum Cum Cum Kg	68.05	01/12/2025	30/05/2026	14	GCC Own	Engineering Section	
GCC 08	Repairing and widening of road from Surabari Rice mill to Kashimpur-Sreepur Road Kazi Market Mr.Malek House via Shaildubi Member Market. (BC Part)	Road	Poor	Emergency	Earth filling, sand filling, End Edging, sub base, Base coarse, wearing coarse, etc.	Ch. 0.0-2725.0 (Various location)	EFW(DrS): 270 Sand Filling: 128.0 SBBC: 120.0 WBMBC: 212.8 TCHD: 800.0 DCPM: 48.0 etc,.....	Cum Cum Cum Cum Sqm Cum	44.85	01/12/2025	30/05/2026	15	GCC Own	Engineering Section	

ICGP B2 GCC 08R	Improvement Of Road By BC AT Shibbari Brt Office To East Direction Omeda Khatun School via Rajbari Dhal.Zourpukur per,Barack meagir Culvert	Road	Poor	Routine Repair	Box Cutting, sand filling, sub-base, base course, wearing course etc....	Ch. 3+625.0 (Various location)	Sand (FM 0.80) filling : 545.620 BC&SGC(450mm):1364.05 SBBC(FM-0.5): 341.013 S&SBC(WG): 1135.478 CWBM(ISSM): 853.743 PCMD@1.2: 3414.970 BMPM: 827.003 TCHD@0.75:9661.620 DCPM: 1599.905 RMP(By-TPC): 665.600 HBPM: 2050.920 TCMD@0.75: 22892.487	Cum Sqm Cum Cum Sqm Cum Sqm Cum Sqm Sqm	644.98	01/12/2025	30/05/2026	16	GCC Own	Engineering Section
ICGP B2 GCC-10 & ICGP B2 GCC-11R	Repairing & widening of Khapara road (starting from Dhaka - Mymenshing road to Vadam road via Tilargati) (Ch-0+00 to Ch-3+810) By RCC Work & Construction of RCC Drain along side of Khapara road lasr part (up to Tilargati road) Ch. 1+375 to Ch-3+810	Road & Drain	Poor	Routine Repair	Box cutting, sand filling, sub base, tac-coat, wearing coarse, RCC work etc.	Ch. 0.0-2000.0 (Various location)	BC&SGC(450mm): 112 Sand Filling: 49.576 SBBC: 21.0 TCHD: 14000.0 25mmDC: 14000.0 RCC-30SCBP: 22.5 SBFS: 33.750 BW (1:4): 5.1 Earth work: 53.760 RCC-30SCCM: 34.5 Deformed Bar: 6934.920 etc,.....	Sqm Cum Cum Sqm Sqm Cum Sqm Cum Cum Kg	153.05	01/12/2025	30/05/2026	17	GCC Own	Engineering Section
ICGP B2 GCC-13	Construction of drain along the side of Nowzour to Zirani Bazar (starting from Zitermour to west direction up to 6.75 Km). (Ch. 00+000 to 6+750)	Drain	Poor	Routine repair	Drain top slab casting, RCC work.	Ch. 0.0-6850.0 (Various location)	RCC-25SCCM: 38.43 Deformed Bar: 4168.22 Etc.....	Cum Kg	18.96	01/12/2025	30/05/2026	18	GCC Own	Engineering Section
ICGP B2 GCC-18	Construction of RCC drain (BADC mor to Mother	Drain	Poor	Routine repair	Drain top slab casting, RCC work.	Ch.0+000 to 1+250	RCC-25SCCM: 7.444 Deformed Bar: 1366.4	Cum Kg	6.77	01/12/2025	30/05/2026	19	GCC Own	Engineering Section

	Textile) from Mission gate to Nager Halot Jora Bridge. Ch.0+000 to 1+250					(Various location)	Etc.....								
ICGP B2 GCC-12R	Repairing & Widening of road from Nowzour to Zirani Bazar (starting from Zitermour to west direction up to 6.85. Km). (Ch. 0+00 to 6+850)	Road	Poor	Routine Repair	Earth work, sand filling, sub base, WBMBC, PCC, Brick work, RCC work etc.....	Ch. 0.0-4450.0 (Various location)	Earth work: 21.6 Sand Filling: 154.56 SBBC: 109.8 WBMBC: 194.711 PCC: 3.375 BW(1:4): 13.5 RCC-25SCBP: 146.4 Deformed Bar: 7374.84 etc,.....	Cum Cum Cum Cum Cum Cum Kg	87.26	01/12/2025	30/05/2026	20	GCC Own	Engineering Section	
ICGP B2 GCC-21 & ICGP B2 GCC-23(c)	a) Improvement of BC road from Mosher market to Kaler Vita mosque via Maglal Mosque. B) Improvement of BC road from Mauglal Dr. Samsul House south side to Kaler Vita mosque via Kholapara Govt. Primary School Ch.0+000 to 2+500. c) Improvement of road by BC from Bagia Diss pukur par to Barek Mollah & Joyartek Primary school to east side Nazem Uddin home. Ch.00 to 1400m.	Road	Poor	Routine Repair	Earth filling, sand filling, End Edging, sub base, Base coarse, wearing coarse, palisading work etc....	(Various location)	EFW(CE): 257.150 Sand Filling: 118.30 SBBC: 88.725 EE(75mm): 660.0 S&SBC: 157.339 PCHD: 591.5 15mmSC: 640.0 DCPM: 23.660 RCC(P+SP): 115.0 RCC(P+DP): 95.0 etc,.....	Cum Cum Cum m Cum Sqm Sqm Cum M M	49.23	01/12/2025	30/05/2026	21	GCC Own	Engineering Section	
ICGP B2 GCC-24	Repairing of BC from MalekerBari	Road	Poor	Routine Repair	TCMD@0.75	Ch. 0.0-2800.0	TCMD@0.75: 12692.500	Sqm	181.76	01/12/2025	30/05/2026	22	GCC Own	Engineering Section	

	(Dhaka-Mymensingh) Road to Bason Chourasta & Link Road.				DCPM	(Various location)	DCPM: 634.625	Cum						
ICGP B2 GCC-27	Repairing of road by BC & HBB start from Vanua to Dakhin Khan Gojalisha Mazar Via Nagar Bhaban & Dirasram bazar.	Road	Poor	Routine Repair	EE(125mm): S&SBC(WG): CWBM(iSSM):PCMD@1.2: TCHD@0.75: DCPM: HBPMM:	Ch. 4+552.0 (Various location)	EE(125mm): 1314.00 S&SBC(WG): 1172.370 CWBM(iSSM): 881.474 PCMD@1.2: 5786.456 TCHD@0.75: 13612.971 DCPM: 544.456 HBPMM: 6602.286	M Cum Cum Sqm Sqm Cum Sqm	232.07	01/12/2025	30/05/2026	23	GCC Own	Engineering Section

Prepared by

Date:

Sohrab
05.02.2025
Sohrab Hossain
Sub-Assistant Engineer
Gazipur City Corporation

Mydul
05.02.25
MD. MYDUL ISLAM
Executive Engineer (Civil)
Zone-4
Gazipur City Corporation

Approved by

Date:

AKM
05.02.25
(এ কে এম হারুনুর রশীদ)
অবস্থায়ক প্রকৌশলী (চ: দা:)
গাজীপুর সিটি কর্পোরেশন
গাজীপুর।