



Bangladesh Accreditation Board (BAB)

91, Motijheel C/A, Dhaka-1000, Tel: +880-2-9513221 Fax: +880-2-9513222

Email: info@bab.org.bd Web: www.bab.org.bd

Certificate of Accreditation


This is to certify that

Inspection Service Division, Bureau Veritas Consumer
Products Services (BD) Ltd.

Tani Villa (2nd & 3rd Floor), House#94, Road#23, Block-A
Banani R/A, Dhaka-1212, Bangladesh

has been granted accreditation in respect of the scope of accreditation described in the attached document, subject to the terms and conditions governing the relevant Conformity Assessment Body (CAB) accreditation

This Inspection Body (Type-A) having met the requirements of ISO/IEC 17020:2012 and the BAB, is accredited for Textile & Textile Products Inspection as described in the associated Scope of Accreditation.



Certificate Number : 05.005.19

Issued on : 30 January 2019

Accreditation Date : 30 January 2019

Valid until : 29 January 2022

Md. Monwarul Islam
Director General

Bangladesh Accreditation Board (BAB)

This certificate has been issued under the authority of Bangladesh Accreditation Act, 2006 and must be returned on request; reproduction must follow guidelines in place at date of issue. For the specific scopes to which this accreditation applies, please refer to the directory of accredited CABs at <http://www.bab.org.bd/directory-of-accredited-cabs>

SCOPE OF ACCREDITATION

(For Inspection Bodies)

CAB Name & Address: Bureau Veritas Consumer Products Services (BVCPS) Bangladesh Ltd., Plot# 130, DEPZ Extension Area, Ganakbari, Savar, Dhaka, Bangladesh

Accreditation Standard: ISO/IEC 17020:2012

Accreditation Date: 30 January, 2019

Certificate Number: 05.005.19

Issued on: 30 January, 2019

Last Amended on: NA

Valid until: 29 January, 2022

Amendment no: NA

Types : A

Head Office or primary location			Additional Locations (If different from Head Office)		
Type (A,B,C)	Inspection Category(Prod uct, Process, Services or Installation)	Inspection Field (and sub-fields)	Range of inspections	Stage of inspection	Inspection requirements or criteria
Address: Plot# 130, DEPZ Extension Area, Ganakbari, Savar, Dhaka, Bangladesh.			1	Tani Villa (2nd & 3rd Floor) House # 94, Road # 23, Block - A, Banani R/A Dhaka – 1213, Bangladesh.	
			2		
			3		
A	Textiles & Apparels	Textiles & Apparels	NA	During Production Inspection (DPI) Final Random Inspection (FRI)	ANSI/ASQ (Sampling), Client Specific Protocol, BVCPS specific protocol & method, inspection field instruction.

END


 Quality Manager