



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Report of Laboratory

Date of Testing: 30-11-2021

Test No: 875

Weather: Sunny

Sl No	Test Item	Unit	Frequency	Detection limit (ECR-1997)	Instrument / Method	River Water	IPR Water	Raw water	Post-sedimentation / Pre-filters Water	Post-filters / Pre-Treated Water	Post-Treated Water
						Sampling Time: 9:00 AM	Sampling Time: 9:20 AM	Sampling Time: 10:30 AM	Sampling Time: 11:30 AM	Sampling Time: 11:42 AM	Sampling Time: 11:55 AM
1	Temperature	°C	day	20-30	Portable analyser-ST300			25.5	25.7	25.5	25.5
2	PH		day	6.5-8.5				7.08	6.87	6.9	7.01
3	Turbidity	NTU	day	<1 NTU	WTW PhotoFlex Turb	146	5.85	5.82	1.07	0.25	0.13
4	Color	pt-co	day	15	Portable analyser-AQ3700			43	0	0	0
5	Suspended Solid	mg/L	day	...				119	3	3	0
6	Taste and Odour		day	Odorless	Manual			Dirty Smell	No Objectionable	No Objectionable	No Objectionable
7	Silica	mg/L	Once a week	...	DR3900						
8	Chloride	ppm	day	150-600	Mercuric Nitrate Titration	40	40				

Remark:



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Report of Laboratory

Date of Testing: 30-11-2021

Test No: 875

Weather: Sunny

Sl No	Test Item	Unit	Frequency	Detection limit (ECR-1997)	Instrument / Method	Post-Treated Water
						Sampling Time: 11:55 AM
1	Total Coliforms	CFU/100 ml	Once a week	0	MC-Media Pad®	0
2	E. Coliforms	CFU/100 ml	Once a week	0		0
Remark:						