



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Report of Laboratory

Date of Testing: 27-11-2021

Test No: 872

Weather: Sunny

Sl No	Test Item	Unit	Frequency	Detection limit (ECR-1997)	Instrument / Method	River Water	IPR Water	Raw water	Post-sedimentation / Pre-filters Water	Post-filters / Pre-Treated Water	Post-Treated Water						
						Sampling Time: 9:31 AM	Sampling Time: 10:37 AM	Sampling Time: 10:55 AM	Sampling Time: 12:00 PM	Sampling Time: 12:12 PM	Sampling Time: 12:27 PM						
1	Temperature	°C	day	20-30	Portable analyser-ST300			27.6	27.2	27.2	27.3						
2	PH		day	6.5-8.5				7.1	6.79	6.89	7.01						
3	Turbidity	NTU	day	<1 NTU	WTW PhotoFlex Turb	83.7	6.78	6.78	0.69	0.28	0.15						
4	Color	pt-co	day	15	Portable analyser-AQ3700			51	8	0	0						
5	Suspended Solid	mg/L	day	...				71	4	4	0	0	0				
6	Taste and Odour		day	Odorless	Manual			Dirty Smell	No Objectionable	No Objectionable	No Objectionable						
7	Oxygen -Dissolved	mg/L	Once a week	6	Portable analyser-ST300D												
8	Nitrogen-Nitrate	mg/L	Once a week	10	DR3900												
9	Nitrogen-Nitrite	mg/L	Once a week	<1													
10	Chloride	ppm	day	150-600	Mercuric Nitrate Titration	40	40										
Remark:																	