



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Record of Plant Apparatus

Date: 12-11-2022

Weather: Sunny

Sl No	Test Item	Unit	Instrument Name	Purshall Flume	Pre Filter-1	Pre Filter-1	CWR
				Time: 9:20 AM	Time: 10:42 AM	Time: 10:45 AM	Time: 11:02 AM
1	pH		KROHNE pH Meter	9.12			7.66
2	Turbidity	NTU	KROHNE Turbidity Meter	28	1.92	0	0.08
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.18
<b>Remark:</b>							