



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Record of Plant Apparatus

Date: 27-12-2022

Weather: Sunny

Sl No	Test Item	Unit	Instrument Name	Purshall Flume	Pre Filter-1	Pre Filter-2	CWR
				Time: 10:42 AM	Time: 11:05 AM	Time: 11:07 AM	Time: 11:22 AM
1	pH		KROHNE pH Meter	8.89			7.64
2	Turbidity	NTU	KROHNE Turbidity Meter	85	1.9	0	0.14
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.22
<b>Remark:</b>							