



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Record of Plant Apparatus

Date: 31-05-2024

Weather: Cloudy

Sl No	Test Item	Unit	Instrument Name	Parshall Flume	Pre Filter-1	Pre Filter-2	CWR
				Time: 08:57 AM	Time: 10:10 AM	Time: 10:12 AM	Time: 10:32 AM
1	pH		KROHNE pH Meter	9.1			7.75
2	Turbidity	NTU	KROHNE Turbidity Meter	39.8	2.1	0	0.15
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.16
Remark:							