



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Record of Plant Apparatus

Date: 09-08-2024

Weather: Cloudy

Sl No	Test Item	Unit	Instrument Name	Parshall Flume	Pre Filter-1	Pre Filter-2	CWR
				Time: 10:16 AM	Time: 10:49 AM	Time: 10:50 AM	Time: 11:11 AM
1	pH		KROHNE pH Meter	8.8			7.52
2	Turbidity	NTU	KROHNE Turbidity Meter	85	2.69	0	0.07
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.24
Remark:							