



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Record of Plant Apparatus

Date: 21-10-2022

Weather: Sunny

Sl No	Test Item	Unit	Instrument Name	Purshall Flume	Pre Filter-1	Pre Filter-1	CWR
				Time: 7:00 AM	Time: 7:35 AM	Time: 7:37 AM	Time: 7:50 AM
1	pH		KROHNE pH Meter	9.28			7.69
2	Turbidity	NTU	KROHNE Turbidity Meter	33.2	3.7	0.1	0.22
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.1
Remark:							